

Kogen P.

INTERMOUNTAIN POWER SERVICE CORPORATION

File: 01.03.10
18.0700

January 7, 1988

Mr. F. Burnell Cordner
Executive Secretary
Utah Air Conservation Committee
Utah Bureau of Air Quality
288 North 1460 West
P.O. Box 16690
Salt Lake City, Utah 84116-0690

Dear Mr. Cordner:

Scheduled And Unscheduled Maintenance Outages During 1988

Intermountain Power Service Corporation was issued a variance from emission limitations as specified in our Approval Order of December 19, 1985 by the Utah Air Conservation Committee during periods of scheduled and unscheduled maintenance outages. As requested by the UBAQ, we are submitting the scheduled maintenance outages for 1988.

1988 SCHEDULED MAINTENANCE OUTAGES


UNIT 1	March 21, 1988 to April 04, 1988 October 31, 1988 to January 23, 1989
UNIT 2	April 18, 1988 to May 02, 1988 October 3, 1988 to October 17, 1988

If excessive emissions occur during these periods of shutdown and/or start-up, IPSC will submit a report to the UBAQ describing the pollutant and the amount emitted within (fifteen) 15 days of each occurrence.

Mr. F. Burnell Cordner
Page Two
January 7, 1988

If you have any questions or comments, please contact Mr. Dennis Killian, IPSC's Superintendent of Technical Services, at (801) 864-4414, extension 6401.

Sincerely,



S. Gale Chapman
President & Chief Operations Officer

ep
RCL:tdt

cc: Bruce E. Blowey
Dennis Killian
Phil Tice
Ron Westlund
Garth Block
Byron Fujikawa
Irwin Stein
Roger Pelote

IP11_002042